


# Field Test Case



 **PLASTICS B.V.**

Vijzelweg 9

5145 NK Waawijk

Tel. : +31 416 343175

Fax.: + 31 416 343716

[info@nabersplastics.com](mailto:info@nabersplastics.com)

[www.nabersplastics.com](http://www.nabersplastics.com)




# Field Test Case




**Customer** : Nabers Plastics Waalwijk  
**Application** : Plastic Moulding machine  
**Brand** : Stork 55/100


**Oil** : Esso Nuto H 46I  
**Carter** : 800 liter  
**NTZ filter** : OLFS-29/1-A-220-1,6

**Dirt reduction in 3 month : ISO 22/19/13 to ISO 14/13/10**



# OFF LINE FILTRATION





## CAUSES OFF BEARING WEAR AND DAMAGE

Oil analysis can detect many of these problems

